Attorney Docket No. 1293.1197

$C_o/C$

THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Byung-in MA et al.

Application No.: 09/815,345

Confirmation No.: 4409

Filed: March 23, 2001

U.S. Patent No.: 7,120,095

Issued: October 10, 2006

For:     APPARATUS FOR GENERATING SEEK DIRECTION DETECTING SIGNAL USING TRACK ERROR AND TRACK CROSS SIGNALS FOR AN OPTICAL PICKUP

**Certificate**

DEC 1 1 2006

ATTENTION

**of Correction**

CERTIFICATE OF CORRECTION

BRANCH

## REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STEIN, MCEWEN & BUI, LLP

Date: DEC. 7, 2006

By: James G. McEwen
Registration No. 41,983

1400 Eye St., N.W.
Suite 300
Washington, D.C. 20005
Telephone: (202) 216-9505
Facsimile: (202) 216-9510

DEC 1 2 2006

# UNITED STATES PATENT AND TRADEMARK OFFICE

# CERTIFICATE OF CORRECTION

PATENT NO : 7,120,095

DATED : October 10, 2006

INVENTOR(S) : Byung-in MA et al.

Column 10, line 33, change "$S_{(p3-p4)}$" to - - $S_{(p3-p2)}$ --

Column 10, line 63, change "detectin" to --detecting --

Column 10, line 64, change "aignal" to -- signal --

Column 11, lines 15 and 16, change "sub-beam" to -- main beam --

Column 11, line 24, change "signal" to -- signals --

Column 13, line 15, change "sub- beam" to -- sub-beam --

Column 13, line 45, start new paragraph after "wherein"

MAILING ADDRESS OF SENDER:
STEIN, MCEWEN & BUI, LLP
1400 Eye St., N.W.
Suite 300
Washington, DC 20005

PATENT NO. 7,120,095

No. of add'l copies
@ 50¢ per page

Ψ

DEC 1 2 2006.